

California Central Coast Lighthouse Conference

Ken Hinshaw

Point Pinos Lighthouse

April 27, 2013

2013 New Outbuildings




Tower Restoration 1



Tower Restoration 2



Tower Restoration 3




Tower Restoration 4



Tower Restoration 5



Rebuilding after 1906 Earthquake



Lantern Room Door 1



Lantern Room Door 2



Gallery



Gallery – Floor Screws



Oil House Door 1



Oil House Door 2



Oil House Door 3




Oil House Door 4



Oil House



Fountain Restoration 1



Capt. Peter C. Nelson at the fountain at Point Pinos Lighthouse, in Monterey, California, where he was the lighthouse keeper in the early 1930s. (Photograph courtesy Susan L. Jones Cota.)

Fountain Restoration 2



Fountain Restoration 3



Gypsy Anchor



Front Porch Floor Rebuild



Window Rebuild




Window Rebuild 1




Window Rebuild 2



Watch Room 1



Watch Room 2



Watch Room 3



Emily Fish Bedroom 1



Emily Fish Bedroom 2



Emily Fish Bedroom – Closet Door



Emily Fish Bedroom - Hardware



01.15.2013

WWII Point Pinos Beach Patrol



WWII Room 1



WWII Room 2



WWII Room 3



WWII Room Flooring



WWII Room – Paint Analysis



Cellar Stairs 1



Cellar Stairs 2



Cellar Stairs 3



Exterior Paint Prep



Point Pinos Lighthouse

Restoration Issues

- Lantern gallery corrosion due to electrolysis
 - aluminum flooring and steel brackets
- Preserving copper roofing and downspouts
 - prepping and painting
- Elastomeric paint removal
 - granite rock
 - important for paint to breathe ?

Point Pinos Lighthouse

Rethinking Interpretation

- How to improve the visitor experience ?
- Consistent with ongoing restoration
- Working cooperatively with another nonprofit

Archives

- Records for a future generation of restorers and historians
- Jumping into the digital world
- Internet accessible

The End

