


Investigation – Rear Porch Closet



**Original
Wood Siding**

Beaver Board Walls



Investigation – Kitchen Attic



New Roof

Old Roof


05.21.2013

Investigation – Rear Porch Attic




- **Confirmed rear porch roof raised**
- **Confirmed original east window**
- **Rear porch painted prior to finishing with Beaver Board**

Modification



Modification



Restoration Target Dates



- Challenges
 - Building modifications over time
 - Historic uncertainties
 - Historic importance
 - Practicality
 - Permitting (City, CCC)
 - Funding
- Decisions
 - No major building changes
 - Exterior as of c1940
 - Individual room restoration dates
 - Work cooperatively with City, CCC

Remodeling - Restoration North Bedroom



Restoration Watch Room



Sample 5	Munsell
White	N 9.5/
Off-white	2.5Y 8.5/1
White	N 9.5/
Blue-gray	10BG 6/1
Off-white	2.5Y 8.5/1
Rose	7.5R 6/4
White	N 9.5/

Remodeling – Restoration Beach Patrol Room



Sample 16	Munsell
White	N 9.5/
Cream	2.5Y 8.5/3
Cream	2.5Y 8/4
White	N 9.5/
Pink	10YR 8/3
Light green	2.5G 8/2
Green	2.5G 5/2
Light green	2.5G 8/2
Light green	2.5GY 7/2
Light green	2.5G 7/2
White	5Y 9/1
Off-white	10YR 8/1
Golden varnish	-----
Cream	2.5Y 8.5/3