

# Preservation / Restoration - Windows



**Building Integrity**

**Tape spring  
balances c1890's**



# Restoration Oil House



# Restoration - Front Porch



**Door and Floor**




# Reconstruction – Fountain & Fence



# Restoration - Tower



# Evaluation – Granite Exterior



**Exterior paint  
removal testing**

# Foghorn Demolished 2012



2000-01-01 Recording Terhorst re audio of foghorn possibly Point Pinos.wma

# Restoration – Lantern



**Galvanic corrosion between aluminum and steel parts of gallery**

